MAX30
Install Guide

[Contents]

I. INSTALLATION

1. Driver Install 1-6


2. Driver Search

2.1 Search automatically for driver 7-9


2.2 Search Manually for driver 10-12

I. INSTALLTION


1. Driver Install




Double Click "MAX30 Setup".




Click "Next".




Click "I Agree".




Click "Next".




Click "Install".




Installing... (wait)




Installing… (wait)







Click "Next".




Installing... (wait)




Click "Finish".



wait.. (It can be take some time depending on your computer's specifications)




Click "OK".




Max30 and Max30 guide file will be created on a wallpaper

※ Caution


If your PC operating system is vista or windows7, follow directions below.




Click "Max30.exe".
Click the right button of mouse.



Click "Property".



Click "Compatibility".



After checking two things, then click "OK'

2. Driver Search

2.1 Search automatically for driver

AL9010



Connect device with PC

Power "ON".




Standby connecting...


ALP-1




Standby connecting...




Click "Browse my computer for driver software".




Click "Browse..."




Click "C:\Program Files\STMicroelectronics\Software\Virtual COM Port Driver".




Click "Next".



Click "Install this driver software anyway".



Installing...



Finish..

2.2 Search Manually for driver

AL9010



Connect device with PC

Power "ON".




Standby connecting…


ALP-1




Standby connecting…




Go to "Control Panel".




Click "System and Security".




Click "Device Manager".




Click "Other devices" or "Ports(COM&LPT)".



check "Virtual COM Port".
Click the right button of mouse.



Click "Update Driver Software...".



Click "Browse my computer for driver software".

start a Update Driver Software
(Go to Page 7)